


Carbonhand Size guide

How to measure your hand to choose the correct glove size as a starting point.

Fit should be snug to ensure accurate sensor activation and optimal assist.

If between sizes, consider sizing down for snug fit.



Carbonhand Size guide

		Hand Length [in]													
		6.25	6.5	6.75	7.0	7.25	7.5	7.75	8.0	8.25	8.5	8.75	9.0	9.25	9.5
Wrist Circumference [in]	4.25								0	0	0	0	0	0	0
	4.5							0	0	0	0	0	0	0	0
	4.75					0	0	0	0	0	0	0	0	0	0
	5.0				0	0	0	0	0	0	0	0	0	0	0
	5.25			0	0	0	0	0	0	0	0	0	0	0	0
	5.5	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	5.75	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	6.0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	6.25	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	6.5	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	6.75	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	7.0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	7.25	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	7.5	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	7.75	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	8.0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	8.25	0	0	0	0	0	0	0	0	0	0	0	0	0	0
8.5	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
8.75	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
9.0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	


X-SMALL

SMALL

MEDIUM

LARGE

X-LARGE



Wrist Circumference